

Moore Custom Woodworking, Inc.

Manufactures of Custom Architectural Millwork
Doors•Windows•Mouldings•S4S

MOULDING WARRANTY

Moore Custom Woodworking, Inc. warrants that its wood mouldings will be free from manufacturing defects which would render them unserviceable or unfit for their normal, recommended use. Natural variations in the color or texture of the wood are not to be considered as defects. Moore Custom Woodworking, Inc. shall have no liability under this warranty or under any implied warranties unless such mouldings have been handled, stored, finished, installed and maintained as noted below. Furthermore, Moore Custom Woodworking, Inc. shall have no liability under this warranty or under any implied warranty for the finish of such mouldings.

Moore Custom Woodworking, Inc. agrees that within a period of one year from delivery date, to repair or replace, without charge, any mouldings which are defective within the meaning of this warranty. Not valid if goods are repaired or replaced without prior consent of Moore Custom Woodworking, Inc.

STORAGE

Do not store mouldings in damp areas or freshly-plastered buildings. Store mouldings on a flat, level surface in a dry, well-ventilated building. Cover to keep clean, but allow circulation. Relative humidity should not be less than 30% or greater than 60%. Moulding should not be subjected to abnormal heat, extreme dryness, humid conditions, or sudden changes therein. They should be conditioned to the average prevailing humidity of the locality before installing.

FINISHING

All wood products require proper surface preparations prior to the application of any finish. To get a consistent stain color and finish, always sand all mouldings with 100-120 grit sandpaper. Never use 180 or 220 grit on raw wood; it can result in polishing, burnishing, or inconsistent stain appearance.

Always seal concealed or backing of moulding to eliminate the possibility of expansion caused by moisture absorption. To ensure uniform color when applying dark stain, it is highly recommended that a wash coat be applied, followed by a light sanding. It is also good practice to apply stains with the mouldings in a horizontal position. This prevents the solvents from evaporating too quickly, which is a common cause of streaks caused by stains setting up before cleaning can be completed.